

To: Peter Butler[butlerpeter2@gmail.com]; wsimon@frontier.net[wsimon@frontier.net]; Steve Fearn[fearneng@rmi.net]; Wall, Dan[wall.dan@epa.gov]; Barb Horn[Barb.Horn@state.co.us]; fpope@bresnan.net[fpope@bresnan.net]; Brent Lewis[b1lewis@blm.gov]
From: Richardson, Lisa
Sent: Wed 2/11/2015 6:27:54 PM
Subject: Fwd: pics of A68
[IMG_20150211_110223_396.jpg](#)
[IMG_20150211_110241_977.jpg](#)
[IMG_20150211_110256_472.jpg](#)

Hello All, Bill was asking about the melting around the A68 gauge for accuracy of usgs flows posted online. Here is what I found this morning. Good flow under what little ice is left. A couple of feet of ice on either side that's probably 6-8 inches thick. I would think gauge is getting pretty close to good working condition.

Lisa

----- Forwarded message -----

From: **Richardson, Lisa** <lrichard@blm.gov>
Date: Wed, Feb 11, 2015 at 11:18 AM
Subject: pics of A68
To: Lisa Richardson <lrichard@blm.gov>

Lisa Richardson

*Abandoned Mine Lands (AML) Program
Silverton BLM, Tres Rios FO
1468 Greene St.
Silverton CO 81433
lrichard@blm.gov*

--

Lisa Richardson

*Abandoned Mine Lands (AML) Program
Silverton BLM, Tres Rios FO
1468 Greene St.
Silverton CO 81433
lrichard@blm.gov*